

SPEEDO HEALER

Istruzioni di installazione cablaggio universale su :

Honda X-ADV 750 DCT

English:

Here is how to install the SH-U01 kit on the X-ADV 750.

All connections take place at the dashboard connector.

- Cut the Pink/Green wire, about 4 cm away from the dash connector, then:
SH Green wire: connect to the Pink/Green at the dash connector side
SH White wire: connect to the Pink/Green at wiring harness side
- SH Red wire: tap the Pink/Blue wire
- SH Black wire: tap the Green/Red wire

Do the SH function tests as per the manual, step #7:

http://www.healtech-electronics.com/docs/SHv4_U01_InstallGuide_en.pdf

Italiano:

Ecco come installare il cablaggio dello SH (Speedohealer) cod. SH-U01 su Honda X-ADV 750 :

I collegamenti vengono effettuati sul connettore della strumentazione.

- Tagliare il filo Rosa/Verde, circa 4 cm lontano dal connettore della strumentazione, quindi:
Collegare il filo **Verde** del cablaggio SH al filo Rosa/Verde che va al connettore della strumentazione.
Collegare il filo **Bianco** del cablaggio SH al filo Rosa/Verde che arriva dal cablaggio.
- Filo **Rosso** del cablaggio SH: Collegarlo con morsetto ruba corrente al filo **Rosa/Blu**
- Filo **Nero** del cablaggio SH: Collegarlo con morsetto ruba corrente al filo **Verde/Rosso**.