

SPEEDO HEALER

Istruzioni di installazione cablaggio universale SH-01 su :

Suzuki GSX-S1000 2015-

English:

https://www.healtech-electronics.com/docs/Supplementary%20Manuals/SH-U01_Suzuki_GSX-S1000_2015-.pdf

We recommend to connect the SH wires at the dashboard connector:

- 1) Cut the Pink/White wire about 2" (5 cm) away from the dashboard plug.
- 2) Connect the SH White to the Pink/White wire end at the wiring harness side.
- 3) Connect the SH Green to the Pink/White wire end at the speedometer side.
- 4) Connect the SH Black wire to the Black/White.
- 5) Connect the SH Red wire the Red/White.

When the installation is done, do the SH signal test procedure as follows:

- Have the ignition key OFF.
 - Press SEL and keep it depressed while you turn the ignition ON.
- [t] (test) is now indicated. Release the button.
- Check: The speedometer should indicate a steady number other than 0.
- Move the bike back and forth so both wheels are turning.
- Check: [t] should be blinking as the wheels turn.

Note: [t] appears on the display like an [E] without the top horizontal bar



Italiano:

MANUALE SUPPLEMENTARE per SH-U01

Si consiglia di collegare i cavi SH al connettore della strumentazione:

- 1) Tagliare il filo Rosa con traccia Bianca a circa 5 cm (2") dal connettore del cruscotto.
- 2) Collegare il filo BIANCO del cablaggio SH al Rosa/Bianco all'estremità del filo lato cablaggio.
- 3) Collegare il filo VERDE del cablaggio SH al Rosa/Bianco all'estremità del filo lato connettore.
- 4) Collegare il filo NERO del cablaggio SH al filo Nero/Bianco.
- 5) Collegare il filo ROSSO del cablaggio SH al filo Rosso/Bianco.

Al termine dell'installazione eseguire la procedura di test del segnale SH nel modo seguente:

- Tenere la chiave di accensione in posizione OFF.
 - Premere SEL e tenerla premuta mentre si gira la chiave su ON.
- Viene ora indicato [T] (test). Rilasciare il pulsante.
- Verifica: il tachimetro deve indicare un numero fisso diverso da 0.
- Muovere la moto avanti e indietro in modo che entrambe le ruote girino.
- Verifica: [t] dovrebbe lampeggiare mentre le ruote girano.

Nota

